



### Project

**Project Name:** Sample Survey  
**Project Description:** CCTV Survey + HPWJ  
**Project Number:** Sample Survey  
**Project Status:** Complete  
**Project Date:** 26/05/2023  
**Inspection Standard:** MSCC5 Sewers & Drainage GB (SRM5 Scoring)





## Table of Contents

Project Name	Project Number	Project Date
Sample Survey	Sample Survey	26/05/2023

Project Information .....	P-1
Scoring Summary .....	P-2
Section: 1; SMH15 > SMH16 (SMH15X) .....	1
Section: 2; SMH11 > SMH16 (SMH11X) .....	2
Section: 3; SMH16 > SMH17 (SMH16X) .....	3
Section: 4; SMH17 > SMH18 (SMH17X) .....	4
Section: 5; SMH18 > OUTFALL1 (SMH18X) .....	5
Section: 6; S1 SPUR > S1 (S1 SPURX) .....	6
Section: 7; S1 > S2 (S1X) .....	7
Section: 8; S2 > S3 (S2X) .....	8
Section: 9; S3 > S4 (S3X) .....	9
Section: 10; S4 > EXTSMH111 (S4X) .....	10
Section: 11; F1 SPUR > F1 (F1 SPURX) .....	11
Section: 12; F1 > F2 (F1X) .....	12
Section: 13; F2 > F3 (F2X) .....	13
Section: 14; F3 > EXTFMH110 (F3X) .....	14



## Project Information

**Project Name**  
Sample Survey

**Project Number**  
Sample Survey

**Project Date**  
26/05/2023

### Client

**Company:** Sample Survey  
**Contact:** Sample Survey  
**Street:** Sample Survey  
**Town or City:** Sample Survey  
**County:** Sample Survey  
**Post Code:** Sample Survey  
**Email:** example@example.com



### Site

**Company:** Sample Survey  
**Street:** Sample Survey  
**Town or City:** Sample Survey  
**County:** Sample Survey  
**Post Code:** Sample Survey

### Contractor

**Company:** Exjet Services  
**Department:** CCTV Team  
**Street:** Unit 30 Woodview Road  
**Town or City:** Paignton  
**County:** Devon  
**Post Code:** TQ4 7HP  
**Phone:** 01803 557000  
**Email:** info@exjet.co.uk



## Scoring Summary

**Project Name**  
Sample Survey

**Project Number**  
Sample Survey

**Project Date**  
26/05/2023

### Structural Defects

Section	PLR	Grade	Description
All inspected pipes are in an acceptable structural condition (< grade 3).			

### Service / Operational Condition

- Grade 3: Best practice suggests consideration should be given to maintenance activities in the medium term.
- Grade 4: Best practice suggests consideration should be given to maintenance activity to avoid potential blockages.
- Grade 5: Best practice suggests that this pipe is at a high risk of backing up or causing flooding.

Section	PLR	Grade	Description
6	S1 SPURX	5	Settled deposits, coarse, 100% cross-sectional area loss
11	F1 SPURX	5	Settled deposits, coarse, 100% cross-sectional area loss

### Abandoned Surveys

Section	PLR	Description
6	S1 SPURX	Survey abandoned
11	F1 SPURX	Survey abandoned

### Information

These scoring summaries are based on the SRM grading from the WRc.



<b>Item No.</b> 1	<b>Insp. No.</b> 1	<b>Date</b> 26/05/23	<b>Time</b> 10:30	<b>Client's Job Ref</b> Not Specified	<b>Weather</b> No Rain Or Snow	<b>Pre Cleaned</b> Yes	<b>PLR</b> SMH15X
<b>Operator</b> Not Specified		<b>Vehicle</b> Not Specified		<b>Camera</b> Crawler	<b>Preset Length</b> Not Specified	<b>Legal Status</b> Highways Drainage	<b>Alternative ID</b> Not Specified

Comments:
Recommendations:

Construction Features					Miscellaneous Features				
Structural Defects					Service & Operational Observations				
STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0



<b>Item No.</b> 2	<b>Insp. No.</b> 1	<b>Date</b> 26/05/23	<b>Time</b> 10:26	<b>Client`s Job Ref</b> Not Specified	<b>Weather</b> No Rain Or Snow	<b>Pre Cleaned</b> Yes	<b>PLR</b> SMH11X
<b>Operator</b> Not Specified		<b>Vehicle</b> Not Specified		<b>Camera</b> Crawler	<b>Preset Length</b> Not Specified	<b>Legal Status</b> Highways Drainage	<b>Alternative ID</b> Not Specified

<b>Town or Village:</b>	Sample Survey	<b>Inspection Direction:</b>	Upstream	<b>Upstream Node:</b>	SMH11
<b>Road:</b>	Sample Survey	<b>Inspected Length:</b>	23.64 m	<b>Upstream Pipe Depth:</b>	
<b>Location:</b>	Other location	<b>Total Length:</b>	23.64 m	<b>Downstream Node:</b>	SMH16
<b>Surface Type:</b>		<b>Joint Length:</b>		<b>Downstream Pipe Depth:</b>	
<b>Use:</b>	Surface water	<b>Pipe Shape:</b>	Circular		
<b>Type of Pipe:</b>	Gravity drain/sewer	<b>Dia/Height:</b>	300 mm		
<b>Flow Control:</b>	No flow control	<b>Material:</b>	Polyethylene		
<b>Year Constructed:</b>	Not Specified	<b>Lining Type:</b>	No Lining		
<b>Inspection Purpose:</b>	Post completion condition survey	<b>Lining Material:</b>	No Lining		

### Recommendations:

Scale:	1:204	Position [m]	Code	Observation	MPEG	Photo	Grade
Depth: m <b>SMH16</b>							
		0.00	MH	Start node, manhole, reference: SMH16	00:00:00		
		0.00	WL	Water level, 5% of the vertical dimension	00:00:01		
		12.03	JN	Junction at 10 o'clock, 150mm dia	00:00:51		
		16.91	JN	Junction at 2 o'clock, 150mm dia	00:01:13		
		23.64	MHF	Finish node, manhole, reference: SMH11	00:01:41		
<b>SMH11</b> Depth: m							

Construction Features					Miscellaneous Features				
Structural Defects					Service & Operational Observations				
STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0



## Section Inspection - 26/05/2023 - SMH16X

Item No. 3	Insp. No. 1	Date 26/05/23	Time 9:45	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned Yes	PLR SMH16X
Operator Not Specified		Vehicle Not Specified		Camera Crawler	Preset Length Not Specified	Legal Status Highways Drainage	Alternative ID Not Specified

Town or Village:	Sample Survey	Inspection Direction:	Downstream	Upstream Node:	SMH16
Road:	Sample Survey	Inspected Length:	17.01 m	Upstream Pipe Depth:	
Location:	Fields, farmland etc	Total Length:	17.01 m	Downstream Node:	SMH17
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Surface water	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	375 mm		
Flow Control:	No flow control	Material:	Concrete		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Post completion condition survey	Lining Material:	No Lining		

Comments:

Recommendations:

Scale: 1:147	Position [m]	Code	Observation	MPEG	Photo	Grade
Depth: m SMH16						
	0.00	MH	Start node, manhole, reference: SMH16	00:00:00		
	0.00	WL	Water level, 5% of the vertical dimension	00:00:01		
	6.17	CN	Connection other than junction at 2 o'clock, 150mm dia	00:00:41		
	8.77	CN	Connection other than junction at 10 o'clock, 150mm dia	00:01:10		
	17.01	MHF	Finish node, manhole, reference: SMH17	00:01:47		
SMH17 Depth: m						

### Construction Features

#### Structural Defects

### Miscellaneous Features

#### Service & Operational Observations

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0



## Section Inspection - 26/05/2023 - SMH17X

Item No. 4	Insp. No. 1	Date 26/05/23	Time 9:48	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned Yes	PLR SMH17X
Operator Not Specified		Vehicle Not Specified		Camera Crawler	Preset Length Not Specified	Legal Status Highways Drainage	Alternative ID Not Specified

Town or Village:	Sample Survey	Inspection Direction:	Downstream	Upstream Node:	SMH17
Road:	Sample Survey	Inspected Length:	34.51 m	Upstream Pipe Depth:	
Location:	Fields, farmland etc	Total Length:	34.51 m	Downstream Node:	SMH18
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Surface water	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	375 mm		
Flow Control:	No flow control	Material:	Concrete		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Post completion condition survey	Lining Material:	No Lining		

Comments:

Recommendations:

Scale:	1:298	Position [m]	Code	Observation	MPEG	Photo	Grade
Depth: m SMH17							
		0.00	MH	Start node, manhole, reference: SMH17	00:00:00		
		0.00	WL	Water level, 5% of the vertical dimension	00:00:01		
		34.51	MHF	Finish node, manhole, reference: SMH18	00:02:16		
SMH18 Depth: m							

### Construction Features

#### Structural Defects

### Miscellaneous Features

#### Service & Operational Observations

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0





<b>Item No.</b> 5	<b>Insp. No.</b> 1	<b>Date</b> 26/05/23	<b>Time</b> 9:59	<b>Client`s Job Ref</b> Not Specified	<b>Weather</b> No Rain Or Snow	<b>Pre Cleaned</b> Yes	<b>PLR</b> SMH18X
<b>Operator</b> Not Specified		<b>Vehicle</b> Not Specified		<b>Camera</b> Crawler	<b>Preset Length</b> Not Specified	<b>Legal Status</b> Highways Drainage	<b>Alternative ID</b> Not Specified

<b>Town or Village:</b>	Sample Survey	<b>Inspection Direction:</b>	Downstream	<b>Upstream Node:</b>	SMH18
<b>Road:</b>	Sample Survey	<b>Inspected Length:</b>	8.25 m	<b>Upstream Pipe Depth:</b>	
<b>Location:</b>	Fields, farmland etc	<b>Total Length:</b>	8.25 m	<b>Downstream Node:</b>	OUTFALL1
<b>Surface Type:</b>		<b>Joint Length:</b>		<b>Downstream Pipe Depth:</b>	
<b>Use:</b>	Surface water	<b>Pipe Shape:</b>	Circular		
<b>Type of Pipe:</b>	Gravity drain/sewer	<b>Dia/Height:</b>	375 mm		
<b>Flow Control:</b>	No flow control	<b>Material:</b>	Concrete		
<b>Year Constructed:</b>	Not Specified	<b>Lining Type:</b>	No Lining		
<b>Inspection Purpose:</b>	Post completion condition survey	<b>Lining Material:</b>	No Lining		

### Recommendations:

Scale:	1:72	Position [m]	Code	Observation	MPEG	Photo	Grade
<div> <div> <div>Depth: m</div> <div>SMH18</div> <div> </div> </div> </div>							
		0.00	MH	Start node, manhole, reference: SMH18	00:00:00		
		0.00	WL	Water level, 5% of the vertical dimension	00:00:01		
		8.25	OFF	Finish node, outfall, reference: OUTFALL1	00:00:54		

Construction Features					Miscellaneous Features				
Structural Defects					Service & Operational Observations				
STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0


## Section Inspection - 26/05/2023 - S1 SPURX

Item No. 6	Insp. No. 1	Date 26/05/23	Time 12:49	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned Yes	PLR S1 SPURX
Operator Not Specified		Vehicle Not Specified		Camera Crawler	Preset Length Not Specified	Legal Status Private Sewer	Alternative ID Not Specified

Town or Village:	Sample Survey	Inspection Direction:	Upstream	Upstream Node:	S1 SPUR
Road:	Sample Survey	Inspected Length:	0.70 m	Upstream Pipe Depth:	
Location:	Fields, farmland etc	Total Length:	0.70 m	Downstream Node:	S1
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Surface water	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	150 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Post completion condition survey	Lining Material:	No Lining		

Comments:

Recommendations:

Scale:	1:50	Position [m]	Code	Observation	MPEG	Photo	Grade
							
		0.00	MH	Start node, manhole, reference: S1	00:00:00		
		0.00	WL	Water level, 5% of the vertical dimension	00:00:00		
		0.70	DER	Settled deposits, coarse, 100% cross-sectional area loss	00:00:11		5
		0.70	SA	Survey abandoned: Unable to pass DER, Ready for future connection	00:00:13		

### Construction Features

#### Structural Defects

### Miscellaneous Features

#### Service & Operational Observations

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	1	10.0	14.3	10.0	5.0



## Section Inspection - 26/05/2023 - S1X

Item No. 7	Insp. No. 1	Date 26/05/23	Time 12:42	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned Yes	PLR S1X
Operator Not Specified		Vehicle Not Specified		Camera Crawler	Preset Length Not Specified	Legal Status Private Sewer	Alternative ID Not Specified

Town or Village:	Sample Survey	Inspection Direction:	Upstream	Upstream Node:	S1
Road:	Sample Survey	Inspected Length:	64.21 m	Upstream Pipe Depth:	
Location:	Fields, farmland etc	Total Length:	64.21 m	Downstream Node:	S2
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Surface water	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	150 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Post completion condition survey	Lining Material:	No Lining		

Comments:

Recommendations:

Scale:	1:554	Position [m]	Code	Observation	MPEG	Photo	Grade
<div><div>Depth: m</div><div>S2</div><div><div></div><div>0.00</div><div>MH</div><div>Start node, manhole, reference: S2</div><div>00:00:00</div></div><div><div></div><div>0.00</div><div>WL</div><div>Water level, 5% of the vertical dimension</div><div>00:00:00</div></div><div><div></div><div>64.21</div><div>MHF</div><div>Finish node, manhole, reference: S1</div><div>00:05:43</div></div><div>S1</div><div>Depth: m</div></div>							

### Construction Features

#### Structural Defects

### Miscellaneous Features

#### Service & Operational Observations

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0



## Section Inspection - 26/05/2023 - S2X

Item No. 8	Insp. No. 1	Date 26/05/23	Time 12:59	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned Yes	PLR S2X
Operator Not Specified		Vehicle Not Specified		Camera Crawler	Preset Length Not Specified	Legal Status Private Sewer	Alternative ID Not Specified

Town or Village:	Sample Survey	Inspection Direction:	Downstream	Upstream Node:	S2
Road:	Sample Survey	Inspected Length:	66.50 m	Upstream Pipe Depth:	
Location:	Fields, farmland etc	Total Length:	66.50 m	Downstream Node:	S3
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Surface water	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	150 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Post completion condition survey	Lining Material:	No Lining		

Comments:

Recommendations:

Scale: 1:574	Position [m]	Code	Observation	MPEG	Photo	Grade
<div><div>Depth: m</div><div>S2</div><div><div></div><div>0.00</div><div>MH</div><div>Start node, manhole, reference: S2</div><div>00:00:00</div></div><div><div>0.00</div><div>WL</div><div>Water level, 5% of the vertical dimension</div><div>00:00:01</div></div><div><div></div><div>66.50</div><div>MHF</div><div>Finish node, manhole, reference: S3</div><div>00:05:56</div></div><div>S3</div><div>Depth: m</div></div>						

### Construction Features

#### Structural Defects

### Miscellaneous Features

#### Service & Operational Observations

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0



## Section Inspection - 26/05/2023 - S3X

Item No. 9	Insp. No. 1	Date 26/05/23	Time 13:15	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned Yes	PLR S3X
Operator Not Specified		Vehicle Not Specified		Camera Crawler	Preset Length Not Specified	Legal Status Private Sewer	Alternative ID Not Specified

Town or Village:	Sample Survey	Inspection Direction:	Downstream	Upstream Node:	S3
Road:	Sample Survey	Inspected Length:	55.62 m	Upstream Pipe Depth:	
Location:	Fields, farmland etc	Total Length:	55.62 m	Downstream Node:	S4
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Surface water	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	150 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Post completion condition survey	Lining Material:	No Lining		

Comments:

Recommendations:

Scale:	1:480	Position [m]	Code	Observation	MPEG	Photo	Grade
<div><div>Depth: m</div><div>S3</div><div><div></div><div>0.00</div><div>MH</div><div>Start node, manhole, reference: S3</div><div>00:00:00</div></div><div><div>0.00</div><div>WL</div><div>Water level, 5% of the vertical dimension</div><div>00:00:01</div></div><div><div></div><div>55.62</div><div>MHF</div><div>Finish node, manhole, reference: S4</div><div>00:04:47</div></div><div>S4</div><div>Depth: m</div></div>							

### Construction Features

#### Structural Defects

### Miscellaneous Features

#### Service & Operational Observations

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0



## Section Inspection - 26/05/2023 - S4X

Item No. 10	Insp. No. 1	Date 26/05/23	Time 13:23	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned Yes	PLR S4X
Operator Not Specified		Vehicle Not Specified		Camera Crawler	Preset Length Not Specified	Legal Status Private Sewer	Alternative ID Not Specified

Town or Village:	Sample Survey	Inspection Direction:	Downstream	Upstream Node:	S4
Road:	Sample Survey	Inspected Length:	4.07 m	Upstream Pipe Depth:	
Location:	Fields, farmland etc	Total Length:	4.07 m	Downstream Node:	EXT SMH111
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Surface water	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	150 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Post completion condition survey	Lining Material:	No Lining		

Comments:

Recommendations:

Scale:	1:50	Position [m]	Code	Observation	MPEG	Photo	Grade
<div><div>Depth: m</div><div>S4</div><div><div></div><div>0.00</div><div>MH</div><div>Start node, manhole, reference: S4</div><div>00:00:00</div></div><div><div></div><div>0.00</div><div>WL</div><div>Water level, 5% of the vertical dimension</div><div>00:00:01</div></div><div><div></div><div>4.07</div><div>MHF</div><div>Finish node, manhole, reference: EXT SMH111</div><div>00:00:41</div></div><div>EXT SMH111</div><div>Depth: m</div></div>							

### Construction Features

#### Structural Defects

### Miscellaneous Features

#### Service & Operational Observations

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0


## Section Inspection - 26/05/2023 - F1 SPURX

Item No.	Insp. No.	Date	Time	Client's Job Ref	Weather	Pre Cleaned	PLR
11	1	26/05/23	14:32	Not Specified	No Rain Or Snow	Yes	F1 SPURX
Operator		Vehicle		Camera	Preset Length	Legal Status	Alternative ID
Not Specified		Not Specified		Crawler	Not Specified	Private Sewer	Not Specified

<b>Town or Village:</b>	Sample Survey	<b>Inspection Direction:</b>	Upstream	<b>Upstream Node:</b>	F1 SPUR
<b>Road:</b>	Sample Survey	<b>Inspected Length:</b>	0.70 m	<b>Upstream Pipe Depth:</b>	
<b>Location:</b>	Fields, farmland etc	<b>Total Length:</b>	0.70 m	<b>Downstream Node:</b>	F1
<b>Surface Type:</b>		<b>Joint Length:</b>		<b>Downstream Pipe Depth:</b>	
<b>Use:</b>	Foul	<b>Pipe Shape:</b>	Circular		
<b>Type of Pipe:</b>	Gravity drain/sewer	<b>Dia/Height:</b>	225 mm		
<b>Flow Control:</b>	No flow control	<b>Material:</b>	Polyvinyl chloride		
<b>Year Constructed:</b>	Not Specified	<b>Lining Type:</b>	No Lining		
<b>Inspection Purpose:</b>	Post completion condition survey	<b>Lining Material:</b>	No Lining		

**Comments:**

**Recommendations:**

Scale:	1:50	Position [m]	Code	Observation	MPEG	Photo	Grade
							
		0.00	MH	Start node, manhole, reference: F1	00:00:00		
		0.00	WL	Water level, 5% of the vertical dimension	00:00:01		
		0.00	DER	Settled deposits, coarse, 100% cross-sectional area loss	00:00:01		5
		0.70	SA	Survey abandoned: Unable to pass DER, Ready for future connection	00:00:10		

### Construction Features

#### Structural Defects

### Miscellaneous Features

#### Service & Operational Observations

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	1	10.0	14.3	10.0	5.0



## Section Inspection - 26/05/2023 - F1X

Item No. 12	Insp. No. 1	Date 26/05/23	Time 14:26	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned Yes	PLR F1X
Operator Not Specified		Vehicle Not Specified		Camera Crawler	Preset Length Not Specified	Legal Status Private Sewer	Alternative ID Not Specified

Town or Village:	Sample Survey	Inspection Direction:	Upstream	Upstream Node:	F1
Road:	Sample Survey	Inspected Length:	64.12 m	Upstream Pipe Depth:	
Location:	Fields, farmland etc	Total Length:	64.12 m	Downstream Node:	F2
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Foul	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	225 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Post completion condition survey	Lining Material:	No Lining		

Comments:

Recommendations:

Scale:	1:553	Position [m]	Code	Observation	MPEG	Photo	Grade
<div><div>Depth: m</div><div>F2</div><div><div></div><div>0.00</div><div>MH</div><div>Start node, manhole, reference: F2</div><div>00:00:00</div></div><div><div></div><div>0.00</div><div>WL</div><div>Water level, 5% of the vertical dimension</div><div>00:00:01</div></div><div><div></div><div>64.12</div><div>MHF</div><div>Finish node, manhole, reference: F1</div><div>00:04:27</div></div><div>F1</div><div>Depth: m</div></div>							

Construction Features

Structural Defects

Miscellaneous Features

Service & Operational Observations

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0





## Section Inspection - 26/05/2023 - F2X

Item No. 13	Insp. No. 1	Date 26/05/23	Time 14:12	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned Yes	PLR F2X
Operator Not Specified		Vehicle Not Specified		Camera Crawler	Preset Length Not Specified	Legal Status Private Sewer	Alternative ID Not Specified

Town or Village:	Sample Survey	Inspection Direction:	Upstream	Upstream Node:	F2
Road:	Sample Survey	Inspected Length:	67.63 m	Upstream Pipe Depth:	
Location:	Fields, farmland etc	Total Length:	67.63 m	Downstream Node:	F3
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Foul	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	225 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Post completion condition survey	Lining Material:	No Lining		

Comments:

Recommendations:

Scale:	1:584	Position [m]	Code	Observation	MPEG	Photo	Grade
<div><div>Depth: m</div><div>F3</div><div><div></div><div>0.00</div><div>MH</div><div>Start node, manhole, reference: F3</div><div>00:00:00</div></div><div><div></div><div>0.00</div><div>WL</div><div>Water level, 5% of the vertical dimension</div><div>00:00:01</div></div><div><div></div><div>67.63</div><div>MHF</div><div>Finish node, manhole, reference: F2</div><div>00:04:47</div></div><div>F2</div><div>Depth: m</div></div>							

### Construction Features

#### Structural Defects

### Miscellaneous Features

#### Service & Operational Observations

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0



## Section Inspection - 26/05/2023 - F3X

Item No. 14	Insp. No. 1	Date 26/05/23	Time 14:03	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned Yes	PLR F3X
Operator Not Specified		Vehicle Not Specified		Camera Crawler	Preset Length Not Specified	Legal Status Private Sewer	Alternative ID Not Specified

Town or Village:	Sample Survey	Inspection Direction:	Downstream	Upstream Node:	F3
Road:	Sample Survey	Inspected Length:	61.65 m	Upstream Pipe Depth:	
Location:	Fields, farmland etc	Total Length:	61.65 m	Downstream Node:	EXT FMH110
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Foul	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	225 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Post completion condition survey	Lining Material:	No Lining		

Comments:

Recommendations:

Scale:	1:532	Position [m]	Code	Observation	MPEG	Photo	Grade
<div><div>Depth: m</div><div>F3</div><div><div></div><div>0.00</div><div>MH</div><div>Start node, manhole, reference: F3</div><div>00:00:00</div></div><div><div></div><div>0.00</div><div>WL</div><div>Water level, 5% of the vertical dimension</div><div>00:00:00</div></div><div><div></div><div>61.65</div><div>MHF</div><div>Finish node, manhole, reference: EXT FMH110</div><div>00:03:46</div></div><div>EXT FMH110</div><div>Depth: m</div></div>							

Construction Features

Structural Defects

Miscellaneous Features

Service & Operational Observations

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0